

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2152

3-16

Date Inspected May 4th

House No. _____

Size of pipe used 6 in

Was lateral at curb? yes

Was attached to main _____


If so how and location from
first manhole down stream 10 ft - North

Distance from first manhole
down stream to ditch at
curb line and depth 2 ft - Depth 7 ft -

Name of Contractor Jess Brunner

Show by diagram relation of lateral to wall of building served.

Lot No 3730



Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office MAY 5 1926

Remarks 10 ft North from manhole to lateral

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2152

PERMIT TO TAP SEWER

Massillon, O., May 3rd 1922

Received of Jessie Bunker fee of \$ 2.00

for which permission is granted 2' Alberts Real Estate

to tap Sanitary sewer, on the W corner side
of Cornell & Cottage Ave., the premises being Lot. No. 3730
Commonwealth St. 7532

919

House No. new. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Bunker - Decker

5/4/22

8100