

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-30 ✓

Nº 2157

Date Inspected May 6 th

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? yes

Name of Contractor

Limback

Was attached to main

Show by diagram relation of lateral to wall of building served.



6 ft

30 ft

7 ft

Laundale. Add

main sewer west →

Signed

A. F. Boyd

Inspector for City

Filed at Engineer's Office

MAY 6 1926

Remarks

New cellar going in.

Diagram run record

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No 2157

Massillon, O., May 5th 1926

Received of H. E. Lumbach fee of \$ 2⁰⁰

for which permission is granted H. Gilly

to tap Sanitary sewer, on the _____ side
of Lawnside Add Ave., the premises being Lot. No. 7-4984
overlook Ave SW St. 8130

House No. _____ Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor H. E. Lumbach