

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-21

Nº 2162

Date Inspected May 11th

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? No

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

House
New



Signed

A. F. Boyd

Filed at Engineer's Office MAY 11 1926

Inspector for City

Remarks

Lateral connected to main 11 ft from straight line on House
House on South Side of St

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2162

PERMIT TO TAP SEWER

Massillon, O., May 11 1909

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

3862
797

733

St.

House No.

New

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

5-11-26
2 PM