## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

NTO	ก	400
No		168

Date Inspected May 17 th	If so how and location from first manhole down stream
House No. // Size of pipe used 4 in	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor Jess. Brunker
Show by diagram relation of lateral to	4
	16 ft-Pipe 13- ft-se
W Cherry St-	in Sewer
W Cherry . St-	-> Was-
Signed A. D. Boyd Inspector for Cit	Filed at Engineer's Office MAY 1 7 1926
Remarks Lateral conected	to lateral at-curb & ft from Strait-line on

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2168

## PERMIT TO TAP SEWER

Massillon, O., 13 19
Received of
Received of fee of \$
for which permission is granted 2 - 15
and the control of th
to tap contact sewer, on the side
of Ave., the premises being Lot. No. 1/77
St.
House No. //
by the City Council, and Rules of the Department of Public Service.
The second secon
Name of Contractor