DATA TO BE ANSWERED BY INSPECTOR D SIGNED WHEN RETURNED

	FOLLOWING DATA TO BE AN
Nº 2169	AND SIGNED WHE
Date Inspected May 14 th	If so how and location from first manhole down stream
House No. / ∂ 3	Distance from first manhole

down stream to ditch at Size of pipe used 4 m curb line and depth Was lateral at curb? 1988

Was attached to main_____

Show by diagram relation of lateral to wall of building served.

Name of Contractor Dess . Brun

Inspector for City

Filed at Engineer's Office MAY 1 4 1926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	Massillon, O.,	mg 132 1926
Received of	and the same of th	fee of \$ 2 0 0
or which permission is granted	10 and of a	
o tap	sewer, on the	Agonald side
eling.	Ave., the premi	ses being Lot. No. 1173
House No. 103 Work to be	e done in accordance with	Ordinance No. 2323, duly passed
by the City Council, and Rules of the		vice.