FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected May 22 House No. 508 412	If so how and location from first manhole down stream
Size of pipe used 4 m	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor & Brunker
Show by diagram relation of lateral to	wall of building served.
	128/ft of Pife
voolb = State	SI
Signed A. F. Bryd Inspector for City	Filed at Engineer's Office MAY 2 4 1926
Remarks Lateral connected	to Satural at cent oft from straw line on

2170

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2170

PERMIT TO TAP SEWER

Massillon, O., 17th 1926
Received of
The state of the s
for which permission is granted
to tap sewer, on the side
of Ave., the premises being Lot. No. 3347
St. 412
House No. 323, duly passed
by the City Council, and Rules of the Department of Public Service.
Name of Contractor 2 - Land