## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED

Date Inspected <u>5-/8-26</u>	If so how and location from first manhole down stream	
House No. 600 404 Size of pipe used	Distance from first manhole down stream to ditch at curb line and depth	
Was lateral at curb?	Name of Contractor Julius Wittman	
Was attached to mainShow by diagram relation of lateral to	wall of building served.	

Filed at Engineer's Office

JUL 1 3 1926

Signed Inspector for City

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2171 PERMIT TO TAP SEWER

Massillon, O., for tool	19
Received of Julius H Attendance fee	of \$ 2 " U
or which permission is granted 14 Qcdo.	
o tap sandam sewer, on the	side
of Ohe Ave., the premises being Lot St.	1761 . No. 662

House No. 600 404. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor & Nath