

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2175

Date Inspected May 24th

If so how and location from
first manhole down stream

House No. 206

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

J. Brunner

House

1/2 ft D
6-8 ft pipe
1/2 ft D

W. Cherry - St

Signed

A. T. Boyd

Inspector for City

Filed at Engineer's Office

MAY 25 1926

Remarks

Lateral connected to lateral at curb 9 1/2 ft from street line on
House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2175

PERMIT TO TAP SEWER

Massillon, O.,

5/19

19

Received of

J. Brunker

fee of \$

2.00

for which permission is granted

J. Brunker

to tap

San.

sewer, on the

West

side

of

N. Erie

Ave., the premises being Lot. No.

Pl. #12

St.

20

House No. 206

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

J. Brunker

5/24/26
1.00 collected
2/11