

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 2177

Date Inspected May 27 If so how and location from
first manhole down stream _____
House No. _____ Distance from first manhole
down stream to ditch at
Size of pipe used 4 in curb line and depth _____
Was lateral at curb? yes Name of Contractor Jess. Bauncker
Was attached to main _____
Show by diagram relation of lateral to wall of building served.

House
New

7 1/2 ft D
30 ft Pipe
8 ft D

Main Sewer
Wallace St -

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office MAY 27 1926

Remarks

Lateral connected to lateral at curb on straight line from house
in front of telephone pole

→ West

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2177

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor