

N^o 2180

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected June 3th If so how and location from
first manhole down stream _____
House No. New Distance from first manhole
down stream to ditch at
Size of pipe used 4 in 910 curb line and depth _____
Was lateral at curb? No back in street 4 ft
Name of Contractor J. Brunken
Was attached to main _____
Show by diagram relation of lateral to wall of building served.

House
New

7 ft D
20 ft Pipe
6 ft D

Plum. St- Main sewer

Lateral 6 ft from man Hole East-

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office JUN 4 1926

Remarks Lateral connected to lateral 4 ft out in street from curb

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2180

PERMIT TO TAP SEWER

Massillon, O.,

May 20th 1926

Received of

fee of \$

for which permission is granted

to tap

sanitary sewer, on the

side

of

Plum Federal Ave NE

Ave., the premises being Lot. No. 535

St.

910

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor