FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED 2183 Date Inspected If so how and location from first manhole down stream.... House No. Distance from first manhole down stream to ditch at Size of pipe used 6 m curb line and depth. Was lateral at curb? Item from Moin Name of Contractor P. E. Bickel Was attached to main_____ Show by diagram relation of lateral to wall of building served. Signed A. T. Boyd
Inspector for City Filed at Engineer's Office 111N 5 1926 Remarks Lateral crosed curb 31 ft from strait line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2183

PERMIT TO TAP SEWER

		Massillor	n, O.,	in and the second secon	19
Received of	PE	Buckel		_fee of \$	<u>C_0</u>
for which permiss	ion is granted	H. La	adder)		
		sewer, on the	\mathcal{E}_{i}	ash	side
of 17tl	h ST SW			ng Lot. No	
House No. 730	Work to	be done in accordance	ce with Ordina	nce No. 2323, du	ily passed
by the City Counc	cil, and Rules of the	Department of Pul	olic Service.		
Name of Contrac	tor 7. E. B	ickel			