FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

5-43

Date Inspected	If so how and location from first manhole down stream	172 47
House No. 744 Size of pipe used	Distance from first manhole down stream to ditch at curb line and depth	17224. 111
Was lateral at curb?		
Was attached to main Show by diagram relation of lateral to	Name of Contractor	

Inspector for City

Filed at Engineer's Office JUN 1 6 1926

Signed

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Massillon, O.,19	21
12430000, 34, 7	
Received of Santaltan fee of \$200	
for which permission is granted e / It that Comp	
for which permission is granted	
to tan sewer, on the	side
to tapsewer, on the	.siuc
	455
of Ave., the premises being Lot. No. 6413	
St.	
744	
House No. 2323, duly pa	issed
±	
and the state of t	
by the City Council, and Rules of the Department of Public Service.	
The Albert Att of the Control of the	
Name of Contractor	
Traine of Contractor	