

Nº 2199

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-28

Date Inspected June 9-1926

If so how and location from
first manhole down stream

House No. Lat 7346 (NEW 5043)

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed

Clark Elser

Inspector for City

Filed at Engineer's Office

JUN 9 1926

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2199

PERMIT TO TAP SEWER

Massillon, O.,

June 9 1926

Received of

M E Lumbach

fee of \$

2.00

for which permission is granted

Roy Lumbach

to tap

San

sewer, on the

West

side

of

Marshall Hill
18th ST NW

Ave., the premises being Lot. No.

5045

7345

House No.

new
445

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Lumbach

9.30
Lumbach