FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

3 - 10

and the second of the second o				
Date Inspected June 11th	If so how and location from first manhole down stream			
House No. New	Distance from first manhole			
Size of pipe used 4 in	down stream to ditch at curb line and depth			
Was lateral at curb? Mes		,		
Was attached to main	Name of Contractor Sinhacon	<u> </u>		
Show by diagram relation of late	ral to wall of building served.	and the second s		
	House			
	620			
	7 ∞			
	Main Sewer			
	Korman	Bol -> Well-		
Signed A & Bayol Anspector	Filed at Engineer's Off	ice JUN 1 2 1926		
Anspector	for City			
Remarks Lateral Con	neited to lateral at curb 17	12 ft from Strait line		
		on House		

No

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2204

## PERMIT TO TAP SEWER

		Massillon, O.,	Variotion 1 4 ?	td. 19
Received of	2 9 7			
	s granted			
	sewei		<i>₹</i>	side
	194		702	5
e de la companya de	· · · · · · · · · · · · · · · · · · ·	St.	<del>-</del>	
House No. 335	Work to be done in a	ccordance with O	rdinance No. 2323, du	ly passed
	d Rules of the Departmen			