

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2210

Date Inspected June 8, 1926

House No. 2104 Lot 157

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main yes


If so how and location from
first manhole down stream _____

Distance from first manhole
down stream to ditch at
curb line and depth 210 feet from Man. Hole down to E. Ditch

Name of Contractor Chas. Spencer

Show by diagram relation of lateral to wall of building served.

4-5. from North
West corner the
ditch pillar
top of shape



Signed Wm. L. Gibson
Inspector for City

Filed at Engineer's Office

JUN 16 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2210

PERMIT TO TAP SEWER

Massillon, O., June 14th 1926

Received of Chas. Stambaugh fee of \$ 2.00

for which permission is granted Frank Stambaugh

to tap Sanitary sewer, on the East side

of Glenwood Ave., the premises being Lot. No. 157
St. 5252

House No. 2106 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas. Stambaugh