Remarks

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED

Date Inspected June 10, 1926
House No. 224, Lat. 198 If so how and location from first manhole down stream Distance from first manhole down stream to ditch at curb line and depth 55 wife from the stream of the curb line and depth 55 wife from the curb line and depth 65 wife from the curb line Size of pipe used Name of Contractor Charles of Contractor Was lateral at curb? Was attached to main \_\_\_\_\_\_ Show by diagram relation of lateral to wall of building served. 4-8 from Mosto Rosch paille 7-0, Deepe. JUN 1 6 1926 Signed Ohn Wesh Filed at Engineer's Office Inspector for City

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2211 PERMIT TO TAP SEWER

	Massillon, O.,	14 1926
Received of Clas Lt	- u	fee of \$2
for which permission is granted Close	Le	
to tap ser	wer, on the	2 ask side
of Elevora	Ave., the premises being St.	ng Lot. No. 158
House No. 2104. Work to be done in	accordance with Ordina	nce No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chan Strong