FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No		223	
		''''''	
13		$\omega \omega$	

Date Inspected June 25 th	If so how and location from first manhole down stream
House No. New	Distance from first manhole down stream to ditch at
Size of pipe used 4 m	curb line and depth
Was lateral at curb? Ma	Name of Contractor Branker & Deshon
Was attached to main	
Show by diagram relation of lateral	to wall of building served.
	6/100
	48/fly Pipe
- Sast	nain sever 2/0
A OF D	
Signed A. J. Boyd Inspector for	Filed at Engineer's Office JUN 3 0 1926
Remarks Lateral Com	nected to main 2,6 ft from strait-line
	40 410 6

for Such.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2235

PERMIT TO TAP SEWER

		Massillon, O.,	0/28	19.
Recei	ived of Brunk	St Desher	fee of \$	200
for which p	ermission is granted	Ter Paul.	i. Lagren de Aue a noto.	
to tap	Sanitary			
of	Burton		ises being Lot. No.	
House No.		done in accordance with	n Ordinance No. 232	3, duly passed
by the City	Council, and Rules of the De	epartment of Public Ser	vice.	
Name of Co	ontractor Branchialt	Mesher		