

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2240

4-52

Date Inspected July 3

House No. 1512 928

Size of pipe used 6 in

Was lateral at curb? yes


Was attached to main

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor Dan Tobin



main sewer → South
Kent St

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office JUL 6 1926

Remarks Lateral connected to lateral at curb 4 ft from street line
on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2240

PERMIT TO TAP SEWER

Massillon, O.,

July 2nd 1926

Received of

Dan Tobin

fee of \$

2.00

for which permission is granted

2 Saloon

to tap

sand aug

sewer, on the

east

side

2713

of

Kent

Ave., the premises being Lot. No.

1352

928

13th ST SE

St.

House No.

1522

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Dan Tobin