FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected fully 12th	If so how and location from first manhole down stream
House No. 725	Distance from first manhole
Size of pipe used 6 in	down stream to ditch at curb line and depth
Was lateral at curb?	
· · · · · · · · · · · · · · · · · · ·	Name of Contractor George Earley
Was attached to main	
Show by diagram relation of lateral to	wall of building served.
	as It-Pila
	82 gr orge
	\8\f
	$\rightarrow N$
	Wasser Steward Commencer and the commencer and t
1 At D , -	Pigeon run road
Signed A Sayat Inspector for Ci	Filed at Engineer's Office JUL 13:00
l = l	1-1 F 1- 1 F 1 1- 1 1 1 1 1 1 1 1 1 1 1
Remarks Lateral Com	ecua w lateral as curo // fi from Strant

No

2251

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	Massillon, O.,				
	Received of	Rachel	Swier	fee of	\$ 200
	- mar a street - m				
for v	vhich permission is	granted		A Company of the	
to to	San	itory	sewer, on the	West	side
to ta	17th ST S	W Road	Ave the or	West	10345 o. <i>5055</i>
OI			St.		
Hou	725 se No	Work to be d	lone in accordance w	vith Ordinance No. 2	2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor George Earley