FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No 2256 Date Inspected If so how and location from first manhole down stream.

House No. 602 Distance from first manhole down stream to ditch at Size of pipe used curb line and depth

Was lateral at curb? Med

Was attached to main. Show by diagram relation of lateral to wall of building served.

Name of Contractor Dan

Main . Dewer

Filed at Engineer's Office Inspector for City

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER No 2256

		Mas	sillon, O.,	ledy 14th	1926
Received of	-7m	Dund	le Co	fee of \$	200
or which permiss	ion is granted	Den	To form		
o tap	f. 2, 2, 24 Shirtherta	sewer, or	1 the	South	side
i Hij	Marid	St.	, the premises	being Lot. No. 2	559
House No.	. Work to	be done in accor	dance with Oro	linance No. 2323,	duly passed
by the City Counc	il, and Rules of the	Department of	Public Service.		

Name of Contractor