## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N? 2268	AND SIGNED	WHEN RETURNED	V
Date Inspected July 30	If so how and location from first manhole down stream		
House No. New Size of pipe used 4 in	Distance from first manhole down stream to ditch at curb line and depth		
Was lateral at curb?	Name of Contractor	has Stroud	
Show by diagram relation of lateral to	wall of building served.	Howe	
		/6 & O. //	

		5-89				
					Mair	. کے۔
		المناسبة المناسبة	دهر ۵	$n \leftarrow N$	orth e	sı-
Signed	A	9.6	Boyd			Filed:
0	100		Inspector for	City		

Eity

Eded to lateral at-curt 4% ft- from Strad

n House

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2268

## PERMIT TO TAP SEWER

	an en de la companya de la companya Na 2000 anya 1949 anya da anya 1940 Na kanangan da manangan anya da anya anya da anya anya anya a	Massillon, O.	July 2 = th 19	26
esta.		P		
Received of	11.60	and the second production of the second	fee of \$2 Ju	
for which permission		and the state of t	2. Soll Commence of the	
to tap	at comp	_sewer, on the	north	_side
of hor	th	Ave., the pre	mises being Lot. No. 277	
House No. 912		ne in accordance wi	th Ordinance No. 2323, duly pa	ıssed
by the City Council, a	nd Rules of the Depa	rtment of Public S	ervice.	
Name of Contractor	Stone		A Company of the Comp	
			and the second s	