

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2272

Date Inspected 8/6/26

If so how and location from
first manhole down stream _____

House No. _____


Distance from first manhole
down stream to ditch at
curb line and depth 585' From M.H. E. Walnut & Lincoln
6' Deep

Was lateral at curb? No

Name of Contractor Early Bros

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



Signed H. Schertzer
Inspector for City

Filed at Engineer's Office

AUG 7 1926

Remarks _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2272

PERMIT TO TAP SEWER

Massillon, O.,

Aug 4th 1926

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. Pt 79
St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor