

Nº 2274

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓
10
33

Date Inspected 8/10/26

House No. #560

Size of pipe used 4" VSP

Was lateral at curb? sewer in Alley


Was attached to main

Show by diagram relation of lateral to wall of building served.

If so how and location from first manhole down stream

Distance from first manhole down stream to ditch at curb line and depth

Name of Contractor



Signed Geo. C. Wallace

Inspector for City

Filed at Engineer's Office

RENNOCK AVE
AUG 11 1926

Remarks When sewer was broken open, was flowing 1/2 full of clean water (looked like surface water). Use 4" Saddle, as a 6" WYE could not be placed very easily

PERMIT TO TAP SEWER

№ 2274

Massillon, O., Aug 6 1911

Received of

fee of \$

for which permission is granted

to tap '_____ sewer, on the _____ side

of Pennock Ave Ave., the premises being Lot. No. 299
St.

House No. 560. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor