

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓
4-7

Nº 2286

Date Inspected

AUG 25 1926

If so how and location from
first manhole down stream

House No.

new

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used

6"

150' - 8'

Was lateral at curb?

Yes

Name of Contractor

P. E. Buckel

Was attached to main

Show by diagram relation of lateral to wall of building served.

Signed

J. W. Maloney

Inspector for City

Filed at Engineer's Office

AUG 30 1926

Remarks

Lateral was to P.L. at given station on Record.
8' W of Sta at Curb Line.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2286

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.
St.

House No. 1016 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor