| N? 2298 | | | |
|--|---|-------------------------------------|-----------------|
| Date Inspected 8-25-26 | If so how and location from first manhole down stream | | |
| House No. #325 | Distance from first manhole down stream to ditch at | | |
| Size of pipe used | curb line and depth | | |
| Was lateral at curb? <u>Mo</u> Was attached to main <u>Yes</u> | Name of Contractor | eo. Early | |
| Show by diagram relation of lateral | to wall of building served. | X V | 113° + 1 |
| | | FRAME DWELLING #325 PORCH, | |
| 2 DON | allace | 8'Below 20 215 Top of find. | A Cof Green St. |

Inspector for City

Filed at Engineer's Office AUG 2 5 926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2298

Name of Contractor

PERMIT TO TAP SEWER

| Massillon, O., 25 1926 |
|--|
| |
| Received of |
| 2 - 21-4 |
| for which permission is granted |
| to tap sewer, on the side |
| of Ave., the premises being Lot. No. 2/83 St. |
| |
| House No. Work to be done in accordance with Ordinance No. 2323, duly passed |
| by the City Council, and Rules of the Department of Public Service. |
| |