FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Aug 31	If so how and location from
	first manhole down stream
House No. 3 0 7	Distance from first manhole
Size of pipe used 6 and	down stream to ditch at curb line and depth
Was lateral at curb?	
Was attached to main yes	Name of Contractor Chas Strouge
Show by diagram relation of latera	I to wall of building served.
Alle State Sta	n) £ 297-22
	[2] [6MB]
. In previous balance to the second	
	8 16 ft Pipe
ing ases of engaging the energy	Same with the second of the se
	G65 ft- from Man hole - 7ft-d
	- Mart- With
Signed A. T. Boyd	Filed at Engineer's Office SEP 1 7 1926
Unspector 10	r City
Remarks Lateral Con	inected to main 21 ft from stront lis
	on House

2306

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	esta irweb electron assi ana inti mati causa (I Massillon, O., 493/3/19
	医外翼神经多种有痛的 医移物 经国民税 语形的语句的 医马克特氏征 医二氏征 医克拉氏管 医克拉氏管 医克拉氏管 医克拉氏管 医克拉氏病 医克拉氏病 化二氯化甲基甲基酚二基酚
Received of	Children of fee of \$200
	granted 6 - C - William 1981 1881 1881
for which permission is	granted
to tap 1a-	land sewer, on the Commen
of 022.	Ave., the premises being Lot. No. 308 St.
	St.
House No. 304	Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

2306