

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2311

6
9

Date Inspected Sept 9 - 1926

If so how and location from
first manhole down stream

House No. 620

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"


Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

J. Wetters



Signed

Clark Elsea
Inspector for City

Filed at Engineer's Office

SEP 11 1926

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2311

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

Fee of \$

for which permission is granted

to tap

sewer, on the

of

3rd ST NE

Ave., the premises being Lot. No. _____
St. _____

House No. 620

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

W. H. Thompson