

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2330

6-18

Date Inspected Sept 18/26

If so how and location from
first manhole down stream

102 ft.

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

102 ft. 6'-6" deep

Was lateral at curb? yes

Name of Contractor

San Tobin

Was attached to main yes

Show by diagram relation of lateral to wall of building served.



Signed

J. Chimer
Inspector for City

Filed at Engineer's Office

SEP 29 1926

Remarks

South side of street

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2330

PERMIT TO TAP SEWER

Massillon, O., Sept 17th 1919

Received of Dan Tobens fee of \$ 2.00

for which permission is granted Nick Pricab

to tap Sanitary sewer, on the South

of McKinley Ave., the premises being Lot. No. 4343
St.

House No. _____ Work to be done in accordance with Ordinance No. 2323, duly pas

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Dan Tobens