

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2388

Date Inspected April 22

If so how and location from
first manhole down stream

House No. 1303

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor Chas Steward

Was attached to main

Show by diagram relation of lateral to wall of building served.

House

43 ft Pipe

South Main Sewer

Signed A. F. Boyd
Inspector for City

Jackson St
Filed at Engineer's Office. APR 23 1927

Remarks Lateral connected to lateral at curb 7 ft from street line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2388

PERMIT TO TAP SEWER

Massillon, O., Oct 23 1911

Received of

fee of \$ 4

for which permission is granted

to tap

sewer, on the

of

...Ave., the premises being Lot. No. 430
St.

House No. 1303. Work to be done in accordance with Ordinance No. 2323, duly passed.

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Chas Brown