

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2408

Date Inspected 11-4-26

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"


Was lateral at curb? No

Name of Contractor

Was attached to main No

Show by diagram relation of lateral to wall of building served.

Chas Strand



Signed

E. B. Coffey

Inspector for City

Filed at Engineer's Office

NOV 4 1926

Remarks

Present lateral not working. Broke it at house
hooked onto new 6" lateral

100
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2408

PERMIT TO TAP SEWER

Massillon, O.,

Nov 4th

19

Received of

Chas. Standa

fee of \$ 2.00

for which permission is granted

Standard - Standish

to tap

Sanitary

sewer, on the

west

5262

of

11th St

10th ST NE Ave., the premises being Lot No.

St.

3285

House No. 845

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Chas. Standa