

Nº 1999

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓
P

Date Inspected Oct 6, 1925

House No. Sat. No. 1443388

Size of pipe used 6 inch

Was lateral at curb?

Was attached to main yes


Show by diagram relation of lateral to wall of building served.

If so how and location from first manhole down stream 42-0. from South Hole West to 4.

Distance from first manhole down stream to ditch at curb line and depth 41-0. from South Hole West. 2-0. Deep.

Name of Contractor Chas. Thout

6-6. from South West corner the Building
1-6. Deep.



Signed Am. Dickson
Inspector for City

Filed at Engineer's Office OCT 8, 1925

Remarks from Main 8-0. line from South Hole West 47-0. 11-6. Deep.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1999

PERMIT TO TAP SEWER

Massillon, O., Oct 5th 1925

Received of Chas. Stroud fee of \$ 2.00

for which permission is granted Mrs Andy Alexander

to tap Saintry sewer, on the north side

of Webb Ave., the premises being Lot. No. 3388 1914 St.

House No. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Chas Stroud