## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2533

Date Inspected March 16  House No. 404  Size of pipe used 4 ms	If so how and location from first manhole down stream.  Distance from first manhole down stream to ditch at curb line and depth.
Was lateral at curb?	Name of Contractor Bess Bunker
Was attached to main	Traine of Contractor
Show by diagram relation of lateral to wall of	f building served. House
lve., Type of Street	
	16 %
House No. 40 6 40	: 20 ft-Pife
2323, duly passed by the City Council, and	Work to be done in some Wife Ordingon No.
	Main Lewer -> East
& ot D	& tate. &/-
Signed A. J. Boyd	Filed at Engineer's Office
Inspector for City	to Abiento de antico con the control and the control of the contro
Remarks Lateral Connec	led to lateral at curb 2 ft from strait
	land on House

Nº 2533

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

mon noticed has not os if
Massillon, O., 3 - 14 - 192 7
Received of Rosa Hemms Heim fee of \$ 200
for which permission is granted.
to tap Sanitary sewer, on the lorth East Cor
of State & Second Ave., Type of Street Pavenient.
the premises being Lot. No. 444 House No. 464
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of
the Department of Public Service.
Name of Contractor Jess Brunker.
NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.
Remarks, Carlotte, Carlott