

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 2550

Date Inspected 3/28-1927

If so how and location from
first manhole down stream

House No. 841

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

HOUSE

841

45'
6" P

MAR 29 1927

Signed Clark Elser

Inspector for City

Filed at Engineer's Office

Remarks

Two Pipes had to be cleaned
in Lateral

curb line
San Sewer
George St

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2550

PERMIT TO TAP SEWER

Massillon, O., March 23 1922

Received of George H. Hutton fee of \$ 2.00

for which permission is granted George Hutton

to tap Sandwich sewer, on the West

of George Ave., Type of Street driv
St.

the premises being Lot. No. Pt 78-79 House No. 841

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule of the Department of Public Service.

Name of Contractor J. Hutton

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.