

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5-6

No. 2552

Date Inspected April 26

If so how and location from
first manhole down stream

House No. 1021 LOT 9704

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

San Tabin

Was attached to main

Show by diagram relation of lateral to wall of building served.



1 1/2

20 ft Pipe

Signed A. T. Boyd

Inspector for City

Filed at Engineer's Office

APR 27 1927

Remarks

lateral connected to lateral at curb 6 1/2 ft from street line on House

RETURNED TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 2552

PERMIT TO TAP SEWER

Massillon, O., August 26 1922

Received of John L. Lohmeyer fee of \$ 3.00

for which permission is granted Dan Lohmeyer

to tap sandstone sewer, on the west

of 1st ST NE Ave., Type of Street paved
9704 St.

the premises being Lot. No. 2557 House No. 1021

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule
the Department of Public Service.

Name of Contractor Dan Lohmeyer

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.