FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED BIJ. Date Inspected April If so how and location from first manhole down stream House No. 1006 - 1008 2 Distance from first manhole down stream to ditch at curb line and depth.....lo bevieed Size of pipe used 4 and Was lateral at curb? MD Name of Contractor Was attached to main yeld Show by diagram relation of lateral to wall of building served. 

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N^{\circ}$  2558

## PERMIT TO TAP SEWER

мой по	inesis bue won o awch dainean				4
	n rei — i epipa 1914 ja Ka <b>a</b> len	The state of the s	(J % - 1) ( ) ( ) ( )	一、新海、胡马、罗门西京(1963年),北方建筑的东	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
for which permission is granted	713-767 h - DEDE (251111 - 15	; <b>E</b> arl			V.
to tap		ewer, on the		ggynis un menann va ua	
of Cerrier	5/ ST NE	Ave., Type o	of Street	Dirt	> ?
the premises being Lot. No.	201		ise No.		
Work to be done in accordance v		No. 2323, duly p	assed by the (	City Council, a	ınd Rul
the Department of Public Service	and the state of t				
Name of Contractor (7)	e, Kar.	//			

NOTE. This permit covers work outside of building only. Any work inside walls of bui is subject to Massillon Board of Health Regulations.