

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3-28

Nº 2559

Date Inspected May 28

If so how and location from
first manhole down stream

House No. New 412

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? No

Was attached to main with stack

Name of Contractor

Geo Bunker
House

Show by diagram relation of lateral to wall of building served.



56 ft Pipe

South Main & Sewer

Signed A. T. Boyd

Inspector for City

Marshall Hill ave

Filed at Engineer's Office

MAY 31 1927

Remarks lateral connected to stack from main 23 1/2 ft from ss line on Ho

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2559

PERMIT TO TAP SEWER

81.00

Massillon, O., March 31 1922

Received of Carlson & Son fee of \$ 2.00

for which permission is granted less Breunher

to tap sanitary sewer, on the main

of Marshall Hill Ave. Ave., Type of Street drain
18th St NW St.

the premises being Lot. No. Pl 2351-2352 House No. 412
5061

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule of the Department of Public Service.

Name of Contractor less Breunher

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.