

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 2565

Date Inspected April 2

If so how and location from
first manhole down stream

House No. 25

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 4 in

Was lateral at curb? No

Was attached to main with hub

Name of Contractor Chas Stroud

Show by diagram relation of lateral to wall of building served.



30 ft Pipe

3 1/2 Main sewer -> East

Alley

Signed A. T. Boyd

Inspector for City

Filed at Engineer's Office **APR 4 1927**

Remarks Lateral connected to main with hub 7 ft from street line on House

South Bril st

OFFICE OF THE I

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

DECEMBER

April 1st

192

Her Ophelia

200

Chas. Stinson

1913
Santayana

10

of 1st and 2nd South St.

du

Q 3251107

20

Handwritten signature

Chas. L. Thompson

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.