FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED _Nº__2637_ Date Inspected June If so how and location from first manhole down stream House No. /235 Distance from first manhole down stream to ditch at Lilla baylaad Size of pipe used and curb line and depth.... Was lateral at curbi Name of Contractor Dan Taken Was attached to main.... Show by diagram relation of lateral to wall of building served. 3 19-431/1 Ordinance No. 2323, duly passed by the City Council, and Kales ar

TO BE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2637

PERMIT TO TAP SEWER

merk nednaci bela wah	oe 11 Assillon, O., Aung. 192
Received of Contract	Blagh fee of \$ 200
for which permission is granted	an Tobuliana mening www.
	sewer, on the
the premises being Lot. No. 4346	St
사람들이 가는 사람들이 살아왔다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들이 되었다.	No. 2323, duly passed by the City Council, and Rul
the Department of Public Service.	
Name of Contractor. Thu Ithu	

NOTE: This permit covers work outside of building only. Any work inside walls of buil is subject to Massillon Board of Health Regulations.