FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 2646Date Inspected June 21 If so how and location from first manhole down stream House No. N. Distance from first manhole down stream to ditch at Size of pipe used 4 ..... curb line and depth. Was lateral at curb? 34 Name of Contractor Oak Was attached to main. Show by diagram relation of lateral to wall of building served.

And D. 1828 - extra for looking for lateral. Caleral in sheat 142 p

FFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2646

## PERMIT TO TAP SEWER

	maispel bar vooi as ii	Massillon, O,	harman Jack
	usu kajuar sa Fi Aldri Fir Fi	Massillon, O,	fee of S 2
Received of Call	94-946	Plaski	#
to tap Janua	and a sewer		non or borthon Vi
of Ene L	I I V = V	to the results of the street	mon mingstone mone
the premises being Lot. No.	2142 <u>-</u> s	t. House No	1514
Work to be done in accordance	ce with Ordinance No. 2		

the Department of Public Service

Name of Contractor Carly Franklin

NOTE. This permit covers work outside of building only. Any work inside walls of buil is subject to Massillon Board of Health Regulations.