

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2659

Date Inspected June 30

If so how and location from
first manhole down stream

House No. New 821

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? yes

Name of Contractor

Was attached to main

Franklin & Early

Show by diagram relation of lateral to wall of building served.



Signed A. F. Boyd

Inspector for City

South ← Main sewer

Third St

Filed at Engineer's Office

JUL 1 1927

Remarks

Lateral connected to lateral at curb 18 1/2 ft from street
Lateral Roded from curb to main O K line on Ho

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2659

PERMIT TO TAP SEWER

Massillon, O., June 27 1922

Received of Franklin & Early fee of \$ 2.00

for which permission is granted Frank Rantier

to tap sanitary sewer, on the west

of Thine 11th ST NE Ave., Type of Street drill
St.

the premises being Lot. No. 390 1224 House No. 813 821

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule:
the Department of Public Service.

Name of Contractor Franklin & Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.