## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 2668 Date Inspected If so how and location from first manhole down stream.

Name of Contractor.,

House No. 3.6 Distance from first manhole down stream to ditch at Size of pipe used. 4. and curb line and depth.... Was lateral at curb? Mo

Was attached to main. W

Show by diagram relation of lateral to wall of building served,

ardinice with Ordinance Not 2123, duly passed by the Chy Connell, and Ritley at

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2668

## PERMIT TO TAP SEWER

	. 11 med noiseat baraha Timed noiseat baraha			en <b>e L</b> oca
	ineri neusael baz viol Lingura nucla tiledus		144 17	192_
Received of	Charing	tronu 6	fee	of \$ 200.
for which permission is	2	in Har		ioni seV
				1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
to tap	tan	sewer, on the	i io nointa manadi	70 7700E
of Je,	nace	Ave., Type of S	itreet de-	<u>~</u>
the premises being Lot.	No. 24 93;	St. / House	No. 357	
Work to be done in acc		e No. 2323, duly passe	ed by the City Cou	ıncil, and Rule

the Department of Public Service.

Name of Contractor has, then d

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.