Nº 2703	AND SIGNED WHEN RETURNED	NSPECTOR V
Date Inspected Aug 19	If so how and location from	
House No. 723 Size of pipe used	first manhole down stream Distance from first manhole down stream to ditch at curb line and depth	
Was lateral at curb? 1900	Name of Contractor Um Hishu	
Was attached to main	Name of Contractor Wm nushu	
Show by diagram relation of lateral to	wall of building served.	
House No.	on many 44 Hours	
uly passed by the City Council, and Rules, of	그리 그들은 걸리 하는 말을 그렇게 되는 것이 🔪 이번 이것이 없었다.	
	My veek sild in the graph of all the second of the second	North
Signed A Of Bound	Riled at Engineer's Office	AUG 2 0 19
Inspector of	Filed at Engineer's Office	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

MIT TO TAP SEWER April noticed has wed as it for which permission is granted the premises being Lot. No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.

Name of Contractor.