

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 2722

7-9

Date Inspected Oct 3 If so how and location from first manhole down stream _____


House No. 1425 Distance from first manhole down stream to ditch at curb line and depth _____

Size of pipe used 6 in _____

Was lateral at curb? yes _____

Was attached to main _____ Name of Contractor Bunker & Deahon

Show by diagram relation of lateral to wall of building served. House



Signed A. T. Boyd Inspector for City Main St & E Filed at Engineer's Office OCT 4 19

Remarks Lateral connected to main with 72 ft from Man Hole
Lateral connected to old line 120 ft from House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2722

PERMIT TO TAP SEWER

Massillon, O., Sept 19 1912

Received of G. J. Jones fee of \$ 2.00

for which permission is granted Bromber & Danks

to tap sanitary sewer, on the South

of Main St. E. Ave., Type of Street parade
Lincoln Way E St.

the premises being Lot. No. Pl. O. 232 House No. 1425

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor Bromber & Danks

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.