FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Nº 2798 Date Inspected Och 26 If so how and location from first manhole down stream..... House No. Melin Distance from first manhole down stream to ditch at Size of pipe used 4 ma curb line and depth..... Was lateral at curb? 1146 Was attached to main_____ Show by diagram relation of lateral to wall of building served. . House No. mance Not 1213, link pissed by de Ony Council and Russ of

vanil political bas well or Massillon, O the premises being Lot. No Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.