FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

0 1-9	마음 하기를 보고 있다면 한 경험에 보면 되었다. 그들은 전에 되는 것은 이 전에 되었다. 그 경험을 보고 있다는 것이 되었다. 생산물이 한 전에 불어 교회에 대한 경험에 되었다. 그 전에 발표를 보고 있다. 그 전에 되었다. 그 전에 발표되는 것은 것은 것이 되었다.
Date Inspected Oct - 3	I so how and location from first manhole down stream.
House No. 2/33	Distance from first manhole down stream to ditch at
Size of pipe used 6	curb line and depth
Was lateral at curb?	Name of Contractor Glo Barly
Show by diagram relation of lateral	to wall of building served. الهسه

Signed A. Boyd Surgalin Way N. W OCT

Inspector for City

Remarks: faleral connected to lateral at Side walk 1 ft from

Atrait line on Hace

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N_{c}^{c} 3069

PERMIT TO TAP SEWER

HIST 2 III	iinisi ima vest es c	Massillon, O. A. 21 1
Received of	4-5-2	fee of \$2
	ورور المرابع المركز والمرابع	Red of \$2
for which permission is grante	مارون) امرون المحمولات والمحمولات المحمولات المحمولات المحمولات المحمولات المحمولات المحمولات المحمولات المحمول	
to tap 16-17-	sew	er, on the Louts
of	184 12	Ne., Type of Street
한 사람은 가는 경기를 가지 않는데 그녀들은 살 때문을 하고 하는 것이다. 아이 왜		St., House No. 2/35
the premises being Lot No.		o 2828 duly passed by the City Council, and B

Name of Contractor Her Early

the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.