

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3077

Date Inspected Oct 1

I so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor

Geo Bruner

Was attached to main

Show by diagram relation of lateral to wall of building served.

House

7 1/2

32 ft Pipe

Main Sewer North →

16th St - S. E.

OCT 2 19

Signed

A. F. Boyd

Inspector for City

Filed at Engineer's Office

Remarks

lateral connected to lateral at curb 3 ft from strai
line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3077

PERMIT TO TAP SEWER

Massillon, O., Sept 28 1908

Received of J. Brumker fee of \$2.00

for which permission is granted H. Stoltz

to tap San sewer, on the W

of 16th St SE Ave., Type of Street drif
St.,

the premises being Lot No. 6554, House No. _____

Work to be done in accordance with Ordinance No. 2923, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor Brumker

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.