## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Oct 9	I so how and location from
House No. 6 6 3	first manhole down stream  Distance from first manhole  down stream to ditch at
Size of pipe used 4	curb line and depth
Was lateral at curb?	Name of Contractor Franklin 4 Early
	l to wall of building served.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N_{0}^{\circ}$  308 $\hat{0}$ 

## PERMIT TO TAP SEWER

	so bew and location from A mannolo down aream.	Massillon, O.,	43/10129
Received of	91.00	Barry Bordon - 19	fee of \$
for which permission	is granted.	<u> </u>	OZ ukananlafin
to tap	THE STATE OF THE S	wer, on the	<u>pidild</u> 229 managanarang
of Grades	0	Ave., Type of Street St.,	arin
the premises being ${ m L}$			663
Work to be done in a the Department of I	mineramine a series program to a final information in a program in the series of the series of the series of t	No. 2328, duly passed by the	ne City Council, an
Name of Contractor	1-a. 10.	-16-Y	
NOTE TA	ic harmit covers morb oute	ide of building only. Any	work inside walls

is subject to Massillon Board of Health Regulations.

\* 1.