

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3107

Date Inspected Nov 1, 1928 I so how and location from
first manhole down stream.

House No. 1450 Distance from first manhole
down stream to ditch at


Size of pipe used 4" curb line and depth approx 6' - 7' deep

Was lateral at curb? Yes.

Was attached to main Yes. Name of Contractor Jess Brunken

Show by diagram relation of lateral to wall of building served.

7' Deep at Curb.



15 North Ju
136
A.A.

Signed H. H. McCall Inspector for City
Filed at Engineer's Office NOV 1 - 1928

Remarks: _____

No. 3107

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Massillon, O., Oct 31st 19

Received of J. E. Lewis Sr. fee of \$ 2.00

for which permission is granted J. E. Brouncker

to tap sanitary sewer, on the East

of 1st St. N.E., Ave., Type of Street paved
St.,

the premises being Lot No. , House No. 1450

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by
the Department of Public Service.

Name of Contractor J. E. Brouncker

NOTE. This permit covers work outside of building only. Any work inside walls of building
is subject to Massillon Board of Health Regulations.