

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

No. 3156

Date Inspected March 8<sup>th</sup>

I so how and location from  
first manhole down stream

House No. 729

Distance from first manhole  
down stream to ditch at  
curb line and depth

Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor

Geo. Early

Was attached to main

Show by diagram relation of lateral to wall of building served.

House

74 1/2

2 1/2 ft Pipe

5

Main Sewer South

Bernard St S. W

FEB 20

Signed

A. F. Royal

Inspector for City

Filed at Engineer's Office

Remarks:

Lateral connected to lateral at curb 1 ft from street  
line on House

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3156

## PERMIT TO TAP SEWER

Massillon, O.,

March 5<sup>th</sup> 19

Received of

*Hes Early*

fee of \$2<sup>00</sup>

for which permission is granted

*Hes Early*

to tap

*sanitary*

sewer, on the

*West*

of

*Beinnard St*

Ave.,

Type of Street

*dr*

St.,

the premises being Lot No.

*4843*

House No.

*729*

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

Name of Contractor

*Hes Early*

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.