

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 3166

Date Inspected April 6

I so how and location from
first manhole down stream

House No. 2341

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Geo Early

Was attached to main

Show by diagram relation of lateral to wall of building served.



6 1/2 50 ft Pipe

Main sewer west 7 1/2 Man Hole →

Signed

A T Boyd

Inspector for City

Filed at Engineer's Office

Lincoln Way E

APR 11 1916

Remarks:

Lateral connected to lateral at main 148 from Man Ho

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3166

PERMIT TO TAP SEWER

Massillon, O. March 25 1920

Received of Geo. Early fee of \$ 2.00

for which permission is granted Mrs. Janett Cunningham

to tap sanitary sewer, on the South

of Lin May E. Ave., Type of Street parade
St.,

the premises being Lot No. 5389, House No. 2341

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Board of Health, and approved by the Department of Public Service.

Name of Contractor Geo. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

1/28/30 ✓

On Lincoln Way East
we lowered lateral
for a distance of 25' 0"
House 2341 Contractor
Geo Early.

City Inspector
Frank B Jones